

Please pay attention to these informations, warning and instruction signs: Use safety glasses Use foot Use hand Use ear and helmet protection protection protection llse filter Use protective Use face Wear clothing mask protection safety vest Ē First aid Eyewash equipment Stretcher Assembly point Extinguishing with Fire, open light and Eating and drinking Access for unauthorized water prohibited smoking prohibited nrohihited persons prohibited Warning of danger Warning of radioactive Warning of dangerous Warning of corrosive electrical voltage of slipping substances or ionizing substances radiation



**For your** 

#### **EMERGENCY PHONE NUMBERS:**

Fire department	122
Rescue	144
Police	133
Safety specialist:	0660/31 31 161
First aid center laboratory:	0664/44 06 771
Control Center:	05771/52 00 445
Poisoning center:	01/406 43 43

#### KIRCHDORFER ZEMENTWERK HOFMANN Gesellschaft m.b.H.

Hofmannstraße 4 | A-4560 Kirchdorf an der Krems Tel: +43 5 7715 200-0 | Fax: +43 5 7715 200-466 sekretariat@kirchdorfer.at

#### www.kirchdorfer-zement.at

We wish you a **safe** and **accident-free stay** at the Kirchdorf cement plant.

# Your **SAFETY** is **IMPORTANT** to us!

No access without suitable protective equipment

Our protective equipment to be used throughout the plant consists of:

- Safety helmet
- Safety glasses
- Safety footwear

In many marked areas, the hearing protection provided must be used!

In case of dust, gas or vapor formation, protect your respiratory organs

### **Basic principles:**

Adhere to the Road Traffic Regulations (StVO) throughout the plant premises! The maximum speed is 10 km/h.

Watch out for moving special vehicles such as forklifts, wheel loaders, bobcats, etc.



Keep traffic/escape routes and emergency exits clear.

Cleaning the workplace after work and proper waste disposal are mandatory.

Always use proper tools/aids.

When working at heights of 2 m or more, use appropriate safety equipment.

#### **External companies** and **coordination**

The plant departments are responsible for the employees and their safety.

Each employee has to pay attention to their own safety as well as to the safety of their colleagues.

Driving authorizations for forklifts, cranes, etc. are only valid with an appropriate driver's license, briefing and an in-house driver's license. This can be obtained from the secretary's office, subject to these conditions.

## **Prohibitions:**

Smoking: only at the marked places Smoking strictly prohibited near the substitute fuels!

The ban on alcohol and narcotics during work must be observed.

Entering areas without proper authorization is prohibited.

Improper storage of hazardous materials is not permitted.

**Discharge** of substances hazardous to water into the sewage system is not

It is forbidden to make drawings of operating equipment, to take photographs or to film.

## **Reporting** and permit requirements



Hot work in areas with fire hazard only with hot work permit



Work in silos and containers only with a silo operator's permit



Work in areas where there is a risk of explosion



Work in railroad areas

Activities that could cause a malfunction in the production process

Reporting of any technical defects

Taking away plant property

Any accident must be reported immediately to the responsible supervisor!

Damage must be reported immediately!

### Accidents and emergencies:

#### If someone is injured, provide first aid. Call the emergency phone number!

Safety data sheets are available at the control station and in the laboratory. In case of accidents with hazardous substances, notify the control station!



















